

Body Mouldings & Trunk (Group 12)

Floor Pans & Rocker Panels

1961-1964 All models. *(12.980)*

Floor Pans

FP-614FFL (FRONT LEFT ONLY)	\$99.50 ea.
FP-614FFR (FRONT RIGHT ONLY)	\$99.50 ea.
FP-614RFL (REAR LEFT ONLY)	\$99.50 ea.
FP-614RFR (REAR RIGHT ONLY)	\$99.50 ea.

Rocker Panels for all 2-door models. *(12.934)*

RP-614L (LEFT OUTER PANEL)	\$99.50 ea.
RP-614R (RIGHT OUTER PANEL)	\$99.50 ea.
RP-614IL (LEFT INNER PANEL)	\$79.50 ea.
RP-614IR (RIGHT INNER PANEL)	\$79.50 ea.

Body Mount Braces behind Rear Wheels. *(12.934)*

BMB-614L (LEFT ONLY)	\$94.50 ea.
BMB-614R (RIGHT ONLY)	\$94.50 ea.

Trunk Panels above Body Mount Braces. *(12.981)*

TP-614L (LEFT ONLY)	\$89.50 ea.
TP-614R (RIGHT ONLY)	\$89.50 ea.

Center Body Brace (curved, under rear floor plan)

CBB-614L (LEFT INNER PANEL)	\$79.50 ea.
CBB-614R (RIGHT INNER PANEL)	\$79.50 ea.



Body Plugs

BP-120 .1/2" Hole Diameter	\$1.50 ea.
BP-580 .5/8" Hole Diameter	\$1.50 ea.
BP-340 .3/4" Hole Diameter	\$1.75 ea.
BP-780 .7/8" Hole Diameter	\$1.75 ea.
BP-100 1" Hole Diameter	\$1.50 ea.
BP-114 1 1/4" Hole Diameter	\$1.50 ea.
BP-112 1 1/2" Hole Diameter	\$1.75 ea.
BP-118 1 1/8" Hole Diameter	\$2.00 ea.

WILDCAT

1967 All. "WILDCAT" Rear 1/4 panel letters. either side.

QM-67W	\$49.50 set
--------------	-------------


1967 All. "WILDCAT" Trunk letters

TL-67W	\$49.50 set
--------------	-------------

Buick

1970 Lesabre Trunk Emblem. "BUICK"

DM-71	\$40.75 ea.
-------------	-------------



Trunk Paint

Correct Speckles in Paint

Finishes Trunk Correctly

Spray Can Allows Easy Access to

Hard to Reach Spaces

TP-642	(Black and Aqua)	\$12.00 ea.
TP-642G	(White & Gray)	\$12.00 ea.

Body Mouldings & Trunk (Group 12)



Trunk Weatherstripping


1961-1975 Trunk weatherstrip. (12.269)
 TW-542-17\$27.50 ea.

1976-1985: Trunk Weatherstrip. Pinchweld Type.
1976-1984 Century & Electra;
1976-1985 Lesabre;
1976-1979 Skyhawk;
1979 Skylark 2-dr. Hatchback;
1980-1985 All Skylark
 TW-761\$59.00 ea.

1986-1991: Trunk Weatherstrip.
1981-1987 Regal;
1986-1991 Skyhawk.
 TW-811\$54.50 ea.

1973-1974 Apollo Hatchback weatherstrip
 HW-734A.....\$46.50 ea.

Trunk Parts


1961-1976 Trunk bumper. Rubber "cap" type. 
 TB-415.....\$1.75 ea.



1961-1976 Trunk bumper.
 Rubber "plug in" type.
 TB-495\$2.25 ea.

Trunk Bumper
1977-1985 Lesabre, Electra;
1977-1981 Century
 TB-777\$2.25 ea.

1961-1972 Spare tire hold down wing nut.
 TN-615\$5.25 ea.



Plastic Side Moulding Clip


1963-1972 For 3/8" wide retention. As required
 MC-600\$1.00 ea.

Trunk Lock Solenoid


1982-1985 Lesabre, Electra;
1982-1984 Century;
1982-1989 Skyhawk
 TLS-829\$49.50 ea.

Trunk Lock & Keys

replacements
1973-1975 All with lock on lid.
 TL-609.....\$16.00 set



1961-1975 Lock on body.
 1961: All;
 1965-1975: All.
 TL-609B.....\$19.25 set



Trunk Lock Gaskets

1961-1975 All as required. As pictured
 KLG-540\$1.25 ea.

1963-1965 Tri-shield Lock Gasket. As required
 TLG-65.....\$3.50 ea.




Trunk Mat

1973-1977 Century & Regal. Green/Gray Felt
 TM-737\$38.50 ea.

1961 thru 1975 Accessory Trunk Mats

Heavy as original with Buick Tri-Shield Logo. Available in Black or Saddle. Either comes with white center logo.

TM-615.....(Black with White Logo).....\$125.00 ea.
 TM-615S.....(Saddle with White Logo).....\$135.00 ea.



We have a small supply of Blems. They may have minor imperfections such as color bleed, rough edge etc. Great for the "driver". Blems are 40% off. Please, at this price, no returns.

TM-6152.....(Black with White Logo).....\$99.00 ea.
 TM-615S2.....(Saddle with White Logo).....\$99.00 ea.