


Carburetion (Group 3)

Carburetor Rebuilding and Restoration Service (3.725)



Each carburetor is totally disassembled and cleaned in a hot tank solution. Then, each component is correctly plated, painted and colored to duplicate it's original factory finish. The carburetor is reassembled using all proper gaskets, pumps, needles and seats, etc. and new correct screws. Finally, all bench adjustments are made to factory specs. This includes correct shimming of the start switch. The result, the best rebuilt and restored carburetor available in the Hobby.

NOTE: This is not an area to skimp on your restoration. Demand the best!

- 1963-1980** All 2bbl Carburetors w/ Bakelite switch
CRS-390.....\$325.00 ea.
- 1963-1980** 4bbl. Carburetor rebuilding service.
CRS-520.....\$379.00 ea.
- 1964-1966** All Carter 2 x 4 Sets
CRS-636D\$699.00 ea.

Carburetor Kits

Carter Carburetors

- 1961-1967** All 2-4BBL and 4BBL.
Numbers: 3088, 89, 3297, 3578, 79,3633, 35, 65, 3826, 27, 3921, 22, 23, 4053, 54, 55, 56, 59, 60, 61, 4179, 80, 81, 4331, 32, 44, 4453, 3645SB, 3646S, 3925SA (Carter AFB 4BBL).
CKC-617.....\$32.50 ea.

Rochester Carburetors

- 1963** With 401 engines. 2GC 2BBL.
Numbers: 7020046, 047, 048, 049, 7023041, 042, 043, 145, 146.
CKR-623.....\$25.25 ea.
- 1963-1966** With 401 engines. 4GC 4BBL.
Numbers: 7023040, 7023143, 7024040, 7025040, 7025140, 7026040.
CKR-636.....\$39.50 ea.

1966-1967

- 1966 All:
1967:Early; 430 engines. 4MV 4BBL.
Numbers: 7025240, 242, 7027146, 147, 148, 149, 7027240, 241, 7036240, 242.
CKR-667.....\$29.50 ea.

- 1967** Late; With 400, 430 and 455 engines. 4MV 4BBL. Numbers: 7027244, 246, 248, 7041304, 305, 306, 307, 308, 309.
1968-1970 Numbers: 7028240, 242, 243, 246, 247, 248, 7029240, 241, 242, 243, 7029246, 7040240, 7040243.
CKR-670.....\$25.25 ea.

- 1968-1974** With 350 and 455 engines. 4MV 4BBL. Numbers: 7028244, 245, 7029244, 245, 7040244, 245, 7041245, 7041544, 7042244, 245, 944, 7043244, 245, 246, 7044244, 246, 544, 7044546, 17054900, 901, 902.
CKR-684.....\$23.00 ea.

- 1970-1974** 350, 455. Numbers: 7040142, 143, 148, 444, 446, 7041142, 143, 442, 7042142, 7042143, 842, 7043142, 143, 144, 7044141, 142, 144, 442, 7044444, 17054651, 17055003, 17057350, 351.
CKR-704.....\$23.75 ea.

- 1970-1973** With 455 high performance engine. 4MV 4BBL. Numbers: 7040246, 247, 7041242, 243, 540, 7042240, 242, 243, 940, 7042942, 7043240, 242, 243, 7044240, 241, 252, 540.
CKR-702.....\$25.75 ea.

- 1975** With 400 engine. 4MC 4BBL. Number: 7045254.
CKR-75.....\$25.75 ea.

- 1975-1976** 455 engine. 4MC, MV 4BBL. Numbers: 7045240, 541, 548, 17056240, 540.
CKR-756.....\$25.75 ea.

Carter Baffle Plate

1963-1966 All with Carter AFB 4bbl. Stainless Steel Plate between carb. & intake manifold. This plate is essential for protection against disintegration of aluminum base of carb. It is also necessary for proper idle and smooth running. Recommended is gasket, baffle plate, gasket.
BP-576\$14.50 ea.

Choke Stove Pipe Replacement Kit

- 1963-1967**
All as required.
CSK-530.....\$15.00 kit

Choke Stove Pipe Insulator


This modern Aramid Fiber sleeve greatly resembles the original. It is heat resistant up to 650 degrees F. White in color. Also excellent for wrapping vapor locked fuel valves. Sold by the foot. **All years.**
PI-300.....\$5.75 ft.


Fuel and Exhaust (Group 3)

Carb. Mounting Gaskets

1963-1965 All;
 1966 All early models (square bore)
 CMG-576\$4.00 ea.


Gas Filters

 1963-1966 Gas filter. For cars without air conditioning.
 GF-636\$10.50 ea.

 1963-1966 For cars with air conditioning.
 GF-636A\$11.50 ea.

1967 All; 1975 All
 GF-675\$3.25 ea.

1968-1975 1968-1974 All;
 1975 All 455 engines.
 GF-682\$3.25 ea.


 All years replacement. Clear in-line Gas filter. Great for near gas tank or frame installation. Important for insuring clean fuel to fuel pump.
 GF-100\$9.50 ea.

Dash Pots


1963-1971 Riviera carburetor dash pot.
 DP-611\$10.75 ea.



Choke Pull Offs



1968-1974 430 and 455 engines with 4BBL Rochester. Front.
 CPO-684\$11.50 ea.



1968-1970 350, 430 & 455 engines. Rochester 4BBL. Rear.
 CPO-681\$13.75 ea.
 1971 455 engines. Rochester 4BBL. Rear.
 CPO-71\$17.50 ea.



Remember!

Check to see that the carburetor number matches that of the part you are ordering.

Ported Vacuum Switches

1968-1974 All except 1972 with three port, two terminals.
 PVS-684\$79.50 ea.
 1972 All three ported with two terminals. (in manifold).
 PVS-72\$79.50 ea.

Rod Clips

1963-1966 Carburetor throttle rod clip. 1/4" rod diameter.
 RC-460\$0.50 ea.



Pinch Clamps (Corbin Clamps)

For fuel lines, vacuum lines & PCV hoses

CARS #:	YEARS:	PRICE:
PC-380	All	3/8" OD hose\$ 1.00 ea.
PC-716	All	7/16" OD hose\$ 1.00 ea.
PC-150	All	1/2" OD hose\$ 1.00 ea.
PC-916	All	9/16" OD hose\$ 1.00 ea.
PC-580	All	5/8" OD hose\$ 1.00 ea.
PC-1116	All	11/16" OD hose\$ 1.25 ea.
PC-100	All	1" OD hose\$ 1.25 ea.

1970-1971 All.
 VT-704\$13.75 ea.

Intake Manifold Plugs


This plug is often rusted out and sometimes missing. Leakage around this plug causes poor carburetion.



1963-1966: All engines with 4-bbl. carburetor
 MP-596\$10.50 ea.

Mass Air Flow Sensor

1985 Riviera
 MAS-85\$69.95 ea.



ECM Calpak ^(3.670)


1984-1985 all Turbo Motors
 EC-857T\$19.50 ea.

Prom Calibrator ^(3.670)

1985 Riviera with turbo Motor
 EP-85TR\$69.50 ea.

Fuel and Exhaust (Group 3)

Air Filter Elements (3.410)



- 1963-1964** 401 and 425 engines with single carburetors.
AF-636.....\$18.25 ea.
- 1964-1966** 425 engines with 2 4BBL carburetors.
AF-646.....\$24.50 ea.
- 1965-1966**
1965-1966: 401-425 engines;
1967: 430 except dual inlet.
AF-657.....\$14.75 ea.
- 1967** Riviera G.S. with dual snorkel air cleaner.
AF-607.....\$13.00 ea.
- 1968; 1970-1975** All.
AF-680.....\$11.00 ea.
- 1969** All.
AF-698.....\$11.00 ea.

Air Cleaner Parts

- 1963-1970** Air cleaner wing nut (1/4"-20 thread).
WN-530.....\$1.75 ea.
- 1971-1980** Air cleaner wing nut (5/16"-18 thread).
WN-710.....\$1.75 ea.


Air Cleaner Heat Pipe

1970-1974 Air cleaner-exhaust manifold.

- Heat pipe.
HP-704 (silver finish).....\$13.25 ea.
HP-704B (black finish).....\$16.50 ea.

Breather Tubes

(Air Cleaner to Rocker Cover) (1.745)




- 1968-1969** All 350 and 400 4BBL.
VT-689.....\$16.00 ea.
- 1970-1971** all.
VT-704.....\$13.75 ea.



Air Cleaner Vacuum Motor

- CARS#: YEARS: APPLICATION: PRICE:**
VM-694L....1968-71..(fits L.H. side of snorkel)....\$23.75 ea.
VM-694R....1968-71..(fits R.H. side of snorkel)....\$23.75 ea.



Crankcase Ventilation Filter On Side Of Air Cleaner

- 1968-1972** All.
CVF-682.....\$ 4.25 ea.

Intake Manifold Gaskets

- 1963-1966** All.
IMG-576.....\$10.75 set
- 1967-1971** All.
IMG-671.....\$32.50 ea.
- 1972-1976** All.
IMG-726.....\$27.00 ea.

Exhaust Parts


- 1968-1972** All. Exhaust manifold head bolt.
3/8"-16 x 1 3/4.
MB-682.....\$1.75 ea.

- Brass Nuts.** Tall. All years as required.
3/8-16. Used on manifolds, pipes,
exhaust, trim etc. Solid Brass
N6P.....\$3.50 pair



Exhaust Manifold Gaskets

- 1963-1966** All.
EMG-576.....\$10.75 pr.
- 1967-1976** All.
EMG-676.....\$14.50 pr.



Exhaust Manifold French Locks




- 1963-1966** All as required. Stainless steel!
FL-576.....\$2.25 ea.
- 1963-1966** All as required. Stainless steel!
FL-626.....\$1.75 ea.

Fuel and Exhaust (Group 3)

Fuel Pumps (3.900)

1963-1965 All. Rebuilding service or sold on an exchange with \$50.00 core charge.
 FP-595RS.....\$78.50 ea.



1963-1965 Replacement Fuel Pump.
 Sold outright no exchange necessary.
 FP-575.....\$38.50 ea.

1966 All without air conditioning.
 FP-66.....\$65.00 ea.

1966 All with Air Condition.
 FP-66A.....\$65.00 ea.

1967-1974 Fuel pump.
 1967-1968: All, except those with fuel pump in tank;
 1971-1974: All except GS.
 FP-674.....\$43.00 ea.

1968-1970 All. (Electric Pump in Gas Tank).
 FP-690.....\$79.50 ea.

1970-1973
 1970: GS stage 1;
 1971-1973: GS.
 FP-683.....\$54.50 ea.


1975-1976 All 455 engines.
 FP-756.....\$43.50 ea.

Fuel Pump Rebuilding Kit

1963-1965 All.
 FPK-575.....\$46.50 ea.

Fuel Pump Block-Off Plates

1963-1976 All as required.
 CP-300.....\$10.50 ea.



Fuel Pump Hardware Kits

1963-1966 all 401,425 engines. Correct bolts/washers
 FPH-406.....\$4.50 ea.

Fuel Injector Seals

1984-1985 Used on all injectors and fuel pressure regulator. 13 needed per car.
 IS-847.....\$2.00 ea.
 IS-847T.....(Set of 15).....\$12.50 set.

Gas Tank Strap Cushions

1963-1975 All.
 SC-350.....\$10.75 pr.

Gas Tank Parts

1963-1965 Riviera gas tank sending unit gasket.
 GG-355.....\$3.75 ea.

1963-1965 Gas door bumper.
 GDB-635.....\$4.50 pr.

1966-1970 Riviera gas tank fuel gauge gasket. (3.112)
 GG-642.....\$4.75 ea.

1973-1981 Riviera gas tank fuel gauge gasket.
 GG-671.....\$4.00 ea.

Gas Tank Bolt Kit

1963-1970 All. Two 3/8-16 x 3" Bolts and two lock nuts.
 Brightly zinc plated.
 GB-610.....\$5.25 kit

Gas Tank Caps




1963-1965 Riviera gas tank cap.
 (vented).
 GC-575.....\$7.25 ea.

1966-1970 Gas tank cap. (non-vented).
 GC-640.....\$7.25 ea.

1971-1974 All.
 GC-714.....\$7.25 ea.

1982-1985 Riviera
 GC-827.....\$11.50 ea.

1982-1985 Riviera (Locking Type with key)
 GC-827L.....\$32.50 ea.



GC-827



GC-827L