


# Carburetion (Group 3)

## Carburetor Rebuilding and Restoration Service (3.725)



Each carburetor is totally disassembled and cleaned in a hot tank solution. Then, each component is correctly plated, painted and colored to duplicate it's original factory finish. The carburetor is reassembled using all proper gaskets, pumps, needles and seats, etc. and new correct screws. Finally, all bench adjustments are made to factory specs. This includes correct shimming of the start switch. The result, the best rebuilt and restored carburetor available in the Hobby.

**NOTE:** This is not an area to skip on your restoration. Demand the best!

- 1963-1980** All 2bbl Carburetors w/ Bakelite switch  
CRS-390.....\$325.00 ea.
- 1963-1980** 4bbl. Carburetor rebuilding service.  
CRS-520.....\$389.00 ea.
- 1964-1966** All Carter 2 x 4 Sets  
CRS-636D .....\$699.00 ea.

## Carburetor Kits

### Carter Carburetors

- 1961-1967** All 2-4BBL and 4BBL.  
Numbers: 3088, 89, 3297, 3578, 79,3633, 35, 65, 3826, 27, 3921, 22, 23, 4053, 54, 55, 56, 59, 60, 61, 4179, 80, 81, 4331, 32, 44, 4453, 3645SB, 3646S, 3925SA (Carter AFB 4BBL). 2 kits needed for 2 x 4 carbs.  
CKC-617.....\$49.50 ea.

### Rochester Carburetors

- 1963** With 401 engines. 2GC 2BBL.  
Numbers: 7020046, 047, 048, 049, 7023041, 042, 043, 145, 146.  
CKR-623.....\$25.25 ea.

- 1963-1966** With 401 engines. 4GC 4BBL.  
Numbers: 7023040, 7023143, 7024040, 7025040, 7025140, 7026040.  
CKR-636.....\$39.50 ea.

- 1966-1967**  
1966 All:  
1967:Early; 430 engines. 4MV 4BBL.  
Numbers: 7025240, 242, 7027146, 147, 148, 149, 7027240, 241, 7036240, 242.  
CKR-667.....\$29.50 ea.

- 1967** Late; With 400, 430 and 455 engines. 4MV 4BBL. Numbers: 7027244, 246, 248, 7041304, 305, 306, 307, 308, 309.

- 1968-1970** Numbers: 7028240, 242, 243, 246, 247, 248, 7029240, 241, 242, 243, 7029246, 7040240, 7040243.  
CKR-670.....\$32.50 ea.

- 1968-1974** With 350 and 455 engines. 4MV 4BBL.  
Numbers: 7028244, 245, 7029244, 245, 7040244, 245, 7041245, 7041544, 7042244, 245, 944, 7043244, 245, 246, 7044244, 246, 544, 7044546, 17054900, 901, 902.  
CKR-684.....\$23.00 ea.

- 1970-1974** 350, 455.  
Numbers: 7040142, 143, 148, 444, 446, 7041142, 143, 442, 7042142, 7042143, 842, 7043142, 143, 144, 7044141, 142, 144, 442, 7044444, 17054651, 17055003, 17057350, 351.  
CKR-704.....\$32.50 ea.

- 1970-1973** With 455 high performance engine. 4MV 4BBL.  
Numbers: 7040246, 247, 7041242, 243, 540, 7042240, 242, 243, 940, 7042942, 7043240, 242, 243, 7044240, 241, 252, 540.  
CKR-702.....\$25.75 ea.

- 1975** With 400 engine. 4MC 4BBL. Number: 7045254.  
CKR-75.....\$25.75 ea.


- 1975-1976** 455 engine. 4MC, MV 4BBL.  
Numbers: 7045240, 541, 548, 17056240, 540.  
CKR-756.....\$25.75 ea.

## Carter Baffle Plate

- 1963-1966** All with Carter AFB 4bbl. Stainless Steel Plate between carb. & intake manifold. This plate is essential for protection against disintegration of aluminum base of carb. It is also necessary for proper idle and smooth running. Recommended is gasket, baffle plate, gasket.  
BP-576 .....\$15.50 ea.

## Choke Stove Pipe Replacement Kit

- 1963-1967**  
All as required.  
CSK-530.....\$17.50 kit



## Choke Stove Pipe Insulator

- This modern Aramid Fiber sleeve greatly resembles the original. It is heat resistant up to 650 degrees F. White in color. Also excellent for wrapping vapor locked fuel valves. Sold by the foot. **All years.**  
PI-300.....\$5.75 ft.


# Fuel and Exhaust (Group 3)

## Carb. Mounting Gaskets



- 1963-1965 All;  
 1966 All early models (square bore)  
 CMG-576 .....\$4.50 ea.  
 1969-1975 All 400,430,455 with Rochester 4BBL  
 CMG-695.....\$4.50 ea.

## Gas Filters



- 1963-1966 Gas filter. For cars without air conditioning.  
 GF-636.....\$10.50 ea.



- 1963-1966 For cars with air conditioning.  
 GF-636A.....\$11.50 ea.



- 1967 All; 1975 All  
 GF-675.....\$3.25 ea.



- 1968-1975 1968-1974 All;  
 1975 All 455 engines.  
 GF-682.....\$3.25 ea.




- All years** replacement. Clear in-line Gas filter. Great for near gas tank or frame installation. Important for insuring clean fuel to fuel pump.  
 GF-100.....\$9.50 ea.

## Dash Pots



- 1963-1971 Riviera carburetor dash pot.  
 DP-611.....\$15.50 ea.



## Choke Pull Offs

- 1968-1974 430 and 455 engines with 4BBL Rochester. Front.  
 CPO-684.....\$11.50 ea.



- 1968-1970 350, 430 & 455 engines. Rochester 4BBL. Rear.  
 CPO-681.....\$13.75 ea.  
 1971 455 engines. Rochester 4BBL. Rear.  
 CPO-71.....\$17.50 ea.

## Ported Vacuum Switches

- 1968-1974 All except 1972 with three port, two terminals.  
 PVS-684.....\$79.50 ea.  
 1972 All three ported with two terminals. (in manifold).  
 PVS-72.....\$79.50 ea.



## Rod Clips

- 1963-1966 Carburetor throttle rod clip. 1/4" rod diameter.  
 RC-460 .....\$0.50 ea.



## Pinch Clamps (Corbin Clamps)

*For fuel lines, vacuum lines & PCV hoses*

CARS #:	YEARS:	PRICE:
PC-380	All	.....3/8" OD hose .....\$ 1.00 ea.
PC-716	All	.....7/16" OD hose.....\$ 1.00 ea.
PC-150	All	.....1/2" OD hose.....\$ 1.00 ea.
PC-916	All	.....9/16" OD hose.....\$ 1.00 ea.
PC-580	All	.....5/8" OD hose.....\$ 1.00 ea.
PC-1116	All	.....11/16" OD hose.....\$ 1.25 ea.
PC-100	All	.....1" OD hose.....\$ 1.25 ea.

## Intake Manifold Plugs


This plug is often rusted out and sometimes missing. Leakage around this plug causes poor carburetion.

- 1963-1966: All engines with 4-bbl. carburetor  
 MP-596.....\$10.50 ea.



## Mass Air Flow Sensor

- 1985 Riviera  
 MAS-85.....\$69.95 ea.



## ECM Calpak <sup>(3.670)</sup>

- 1984-1985 all Turbo Motors  
 EC-857T.....\$19.50 ea.

## Prom Calibrator <sup>(3.670)</sup>

- 1985 Riviera with turbo Motor  
 EP-85TR .....\$69.50 ea.

# Fuel and Exhaust (Group 3)

## Air Filter Elements (3.410)

1963-1964 401 and 425 engines with single carburetors.

AF-636.....\$18.25 ea.

1964-1966 425 engines with 2 4BBL carburetors.

AF-646.....\$24.50 ea.

### 1965-1966

1965-1966: 401-425 engines;  
1967: 430 except dual inlet.

AF-657.....\$14.75 ea.

1967 Riviera G.S. with dual snorkel air cleaner.

AF-607.....\$15.00 ea.

### 1968; 1970-1975 All.

AF-680.....\$11.00 ea.

### 1969 All.

AF-698.....\$11.00 ea.

## Air Cleaner Parts

1963-1970 Air cleaner wing nut (1/4"-20 thread).

WN-530 .....\$1.75 ea.

1971-1980 Air cleaner wing nut (5/16"-18 thread).

WN-710 .....\$1.75 ea.

## Air Cleaner Heat Pipe

1970-1974 Air cleaner-exhaust manifold.

Heat pipe.


HP-704 (silver finish) .....\$13.25 ea.

HP-704B (black finish) .....\$16.50 ea.

## Breather Tubes


(Air Cleaner to Rocker Cover) (1.745)

Breather Tube



1968-1969 All 350 and 400 4BBL.  
VT-689 .....\$17.50 ea.

1970-1971 all.  
VT-704.....\$15.00 ea.




## Air Cleaner Vacuum Motor

**CARS#: YEARS: APPLICATION: PRICE:**

VM-694L....1968-71..(fits L.H. side of snorkel)....\$23.75 ea.

VM-694R....1968-71..(fits R.H. side of snorkel)....\$23.75 ea.



## Crankcase Ventilation Filter On Side Of Air Cleaner

1968-1972 All.

CVF-682.....\$ 4.50 ea.

## Intake Manifold Gaskets

1963-1966 All.

IMG-576.....\$11.50 set

1967-1971 All.

IMG-671 .....\$32.50 ea.

1972-1976 All.

IMG-726 .....\$27.00 ea.

## Exhaust Parts

1968-1972 All. Exhaust manifold head bolt.

3/8"-16 x 1 3/4.

MB-682.....\$1.75 ea.

**Brass Nuts.** Tall. All years as required.

3/8-16. Used on manifolds, pipes, exhaust, trim etc. Solid Brass

N6P.....\$3.50 pair




## Exhaust Manifold Gaskets

1963-1966 All.

EMG-576.....\$10.75 pr.

1967-1976 All.

EMG-676.....\$14.50 pr.



## Exhaust Manifold French Locks



1963-1966 All as required. Stainless steel!

FL-576 .....\$3.25 ea.


1963-1966 All as required. Stainless steel!

FL-626 .....\$1.75 ea.

# Fuel and Exhaust (Group 3)

## Fuel Pumps (3.900)

**1963-1965** All. Rebuilding service or sold on an exchange with \$50.00 core charge.  
 FP-595RS.....\$88.50 ea.



**1963-1965** Replacement Fuel Pump.  
 Sold outright no exchange necessary.  
 FP-575.....\$38.50 ea.

**1966** All without air conditioning.  
 FP-66.....\$65.00 ea.

**1966** All with Air Condion.  
 FP-66A.....\$65.00 ea.

**1967-1974** Fuel pump.  
 1967-1968: All, except those with fuel pump in tank;  
 1971-1974: All except GS.  
 FP-674.....\$43.00 ea.

**1968-1970** All. (Electric Pump in Gas Tank).  
 FP-690.....\$79.50 ea.

**1970-1973**  
 1970: GS stage 1;  
 1971-1973: GS.  
 FP-683.....\$54.50 ea.


**1975-1976** All 455 engines.  
 FP-756.....\$43.50 ea.

## Fuel Pump Rebuilding Kit

**1963-1965** All.  
 FPK-575.....\$46.50 ea.

## Fuel Pump Block-Off Plates

**1963-1976** All as required.  
 CP-300.....\$10.50 ea.



## Fuel Pump Hardware Kits

**1963-1966** all 401,425 engines. Correct bolts/washers  
 FPH-406.....\$4.50 ea.

## Fuel Injector Seals

**1984-1985** Used on all injectors and fuel pressure regulator. 13 needed per car.  
 IS-847.....\$2.00 ea.  
 IS-847T.....(Set of 15).....\$12.50 set.

## 1979-1985 Gas Tank

**1979-1980** All exc. 350 engine;  
**1981-1983** All;  
**1984-1985** All with 307Y  
 Includes filler Neck. Shipping about \$95  
 GT-795.....\$199.50 ea.  
 GS-795.....(Strap Cushions for above).....\$24.50 pair

## Gas Tank Parts

**1963-1965** Riviera gas tank sending unit gasket.  
 GG-355.....\$3.75 ea.  
**1963-1965** Gas door bumper.  
 GDB-635.....\$4.75 pr.

**1963-1970** All. Gas Tank Bolt Kit. Two 3/8-16 x 3" Bolts and two lock nuts. Brightly zinc plated.  
 GB-610.....\$5.25 kit

**1963-1985** All. Gas Tank Strap Cushions  
 SC-350.....\$12.75 pr.

**1966-1970** Riviera gas tank fuel gauge gasket. (3.112)  
 GG-642.....\$4.75 ea.

**1973-1985** Riviera gas tank fuel gauge gasket.  
 GG-671.....\$11.50 ea.

## Gas Tank Caps




**1963-1965** Riviera gas tank cap. (vented).  
 GC-575.....\$7.25 ea.

**1966-1970** Gas tank cap. (non-vented).  
 GC-640.....\$7.25 ea.

**1971-1974** All.  
 GC-714.....\$9.50 ea.

**1982-1985** Riviera  
 GC-827.....\$11.50 ea.

**1982-1985** Riviera (Locking Type with key)  
 GC-827L.....\$32.50 ea.



GC-827



GC-827L